

Filled out by: **G J Demers**

Date / Time: 09/06/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>Mt. Holly</u>
Valuation Sheet: V 3 / 39	Valuation Stationing: <u>2007 + 68</u>
Mile Post: B 38.01	GPS Coordinates: N: <u>43.44725</u> W: <u>72.85088</u>

Crossing Name: GATES ROAD

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 859 874 E

Signaled ☐ Yes ☒ No Crossbucks ☒ Yes ☐ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Other WHEEL CUT

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 105 DY Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____







