

Filled out by: **G J Demers**

Date / Time: 09/10/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>WALLINGFORD</u>
Valuation Sheet: V 3 / 40	Valuation Stationing: <u>2085 + 10</u>
Mile Post: B 39.47	GPS Coordinates: N: <u>43.44958</u> W: <u>72.87752</u>

Crossing Name: EAST WALLINGFORD

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 859 878 G

Signaled ☒ Yes ☐ No Crossbucks ☐ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel

Flangeway ☐ Rubber ☒ Rail ☐ Plank ☒ Other WNSBL CUT (NORTH RAIL)

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 105 DY Rail Condition ☐ Good ☒ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____







