

Filled out by: G J Demers

Date: 05 / 28 / 2014

### Crossing Inspection Form

|                                                |                                                              |
|------------------------------------------------|--------------------------------------------------------------|
| Railroad: <b>WACR M&amp;BD</b>                 | Town: <u>MONTPELIER</u>                                      |
| Valuation Sheet:<br>Page <u>3</u> of <u>18</u> | Valuation Stationing:<br><u>114 + 74</u>                     |
| Mile Post:<br><u>M 2.17</u>                    | GPS Coordinates:<br>N: <u>44 15 01</u><br>W: <u>72 33 50</u> |

Crossing Name: \_\_\_\_\_

Type: ☐ Public ☐ Private ☒ Farm ☐ Other \_\_\_\_\_

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other \_\_\_\_\_

AAR DOT Number \_\_\_\_\_

Signaled ☐ Yes ☒ No      Crossbucks ☐ Yes ☒ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel ☐ Planks

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Wheel cut ☐ Other \_\_\_\_\_

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 85      Rail Condition ☐ Good ☒ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_















