

UPDATE

Filled out by: G J Demers

Date / Time: 05/06/13

Switch Inspection Form

Railroad: GMRC	Town: <u>ROCKINGHAM</u>
Valuation Sheet: V 3 / 1	Valuation Stationing: <u>2 + 47.7</u>
Mile Post: B 0.05	GPS Coordinates: N: <u>43.13637</u> W: <u>72.44136</u>

Switch Name: PLATFORM

Type: ☐ Main Track ☐ Siding ☒ Spur ☒ Yard ☐ Private ☐ Other _____

Rail Size / Type 90 DY Condition ☐ Good ☒ Fair ☐ Poor

Turnout Type #9 ☐ Right Hand ☒ Left Hand ☐ Equilateral

Switch Point Length 16'6" Tie Condition ☐ Good ☒ Fair ☐ Poor

Frog Type ☒ Ridgid ☐ Solid Manganese ☐ Spring ☐ Other _____

Frog Length 12 FT 0 IN Condition ☐ Good ☒ Fair ☐ Poor

Switch Stand ☒ High ☐ Intermediate ☐ Ground ☐ Ergonomic ☐ Other

Guardrail Type ☐ Bolted rail ☒ cast ☐ Other _____

Signaled ☐ Yes ☒ No Security ☐ Switch Lock ☒ Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



