

Filled out by: G.J.DEMERS

Date: 09 / 28 / 2011

Switch Inspection Form

Railroad: WACR CRL B/S	Town: NEWBURY
Valuation Sheet: V 43 / 41	Valuation Stationing: 2142 + 51
Mile Post: D 0.32	GPS Coordinates: N: 44 09.300 W: 72 02.672

Switch Name: NORTH WYE (REMOVED) 05/01/12

Type: ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Private ☐ Other _____

Rail Size / Type 100 NH Condition ☐ Good ☐ Fair ☐ Poor

Turnout Type _____ ☐ Right Hand ☒ Left Hand ☐ Equilateral

Switch Point Length _____ FT _____ IN Tie Condition ☐ Good ☐ Fair ☐ Poor

Frog Type ☐ Ridgid ☒ Solid Manganese ☐ Spring ☐ Other _____

Frog Length _____ FT _____ IN Condition ☐ Good ☐ Fair ☐ Poor

Switch Stand ☒ High ☐ Intermediate ☐ Ground ☐ Ergonomic ☐ Other

Guardrail Type ☒ Bolted rail ☐ cast ☐ Other _____

Signaled ☐ Yes ☒ No Security ☒ Switch Lock ☐ Keeper

Number of Photos Taken 2

Remedial Action (if any) _____













