

Filled out by: G.J.DEMERS

Date: 08 / 08 / 2011

### Switch Inspection Form

|                                   |                                                    |
|-----------------------------------|----------------------------------------------------|
| Railroad: <b>WACR CRL B/S</b>     | Town: <b>HARTFORD</b>                              |
| Valuation Sheet:<br><b>V 43 /</b> | Valuation Stationing:<br><b>+</b>                  |
| Mile Post:<br><b>D .</b>          | GPS Coordinates:<br>N: 43 38 .311<br>W: 72 19 .490 |

Switch Name: #3 SOUTH (WRT SOUTH YARD)

Type: ☐ Main Track ☐ Siding ☐ Spur ☒ Yard ☐ Private ☐ Other \_\_\_\_\_

Rail Size / Type 100 NH Condition ☐ Good ☒ Fair ☐ Poor

Turnout Type #9 ☒ Right Hand ☐ Left Hand ☐ Equilateral

Switch Point Length 15 FT 0 IN Tie Condition ☐ Good ☒ Fair ☐ Poor

Frog Type ☐ Ridgid ☒ Solid Manganese ☐ Spring ☐ Other \_\_\_\_\_

Frog Length 8 FT 5 IN Condition ☒ Good ☐ Fair ☐ Poor

Switch Stand ☐ High ☒ Intermediate ☐ Ground ☐ Ergonomic ☐ Other \_\_\_\_\_

Guardrail Type ☐ Bolted rail ☐ cast ☒ Other SELF GUARDED FROG

Signaled ☐ Yes ☒ No Security ☐ Switch Lock ☒ Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_



