

Filled out by: G.J.DEMERS

Date: 09/28/2011

### Switch Inspection Form

|                                      |                                                                |
|--------------------------------------|----------------------------------------------------------------|
| Railroad: <b>WACR CRL L/S</b>        | Town: <b>RYEGATE</b>                                           |
| Valuation Sheet:<br><b>V 43 / 45</b> | Valuation Stationing:<br><b>2375 + 41</b>                      |
| Mile Post:<br><b>L 59.20</b>         | GPS Coordinates:<br>N: <b>44 12.813</b><br>W: <b>72 03.580</b> |

Switch Name: SOUTH BELL (OUT OF SERVICE)

Type: ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Private ☐ Other \_\_\_\_\_

Rail Size / Type 100 REHF Condition ☐ Good ☐ Fair ☐ Poor

Turnout Type # 11 ☐ Right Hand ☒ Left Hand ☐ Equilateral

Switch Point Length 22 FT 0 IN Tie Condition ☐ Good ☐ Fair ☐ Poor

Frog Type ☐ Ridgid ☐ Solid Manganese ☒ Spring ☐ Other \_\_\_\_\_

Frog Length 17 FT 0 IN Condition ☒ Good ☐ Fair ☐ Poor

Switch Stand ☒ High ☐ Intermediate ☐ Ground ☐ Ergonomic ☐ Other

Guardrail Type ☐ Bolted rail ☒ cast ☐ Other \_\_\_\_\_

Signalled ☐ Yes ☒ No Security ☒ Switch Lock ☐ Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_

~~OUT OF SERVICE~~ 05/01/14  
(STRAIGHT TRACK)







