






































"SHEAR BRACE" AT PIER 1 NORTH SIDE
2/3'S CRACKED THROUGH





8.5" $\frac{0.2}{12}$

8 1/4" $\frac{11}{16}$ "

5/98

8" $\frac{1}{4}$ " - 8 1/4"

8 1/4" $\frac{0.2}{12}$
























9M
100212
Site

SIGNIFICANT WEAR OF GUSSET ALONG PIN SLOT
AT SOUTHEAST PIN CONN.

















1/2 IN 3'
4/2000
Q 4005















4.5" Deep
Up stream Truss
Bottom chord
East Face
2nd Panel
Point
of
Turn







