

A photograph of a concrete wall. On the left side, there is a vertical column of four large, rectangular concrete blocks. A dark, vertical crack runs down the right side of this column, starting from the top and extending nearly to the bottom. The rest of the wall is made of smaller, irregular concrete blocks. At the bottom left, there is some dark soil and some dry, yellowish-brown grass or weeds. In the bottom right corner, there is a date stamp in orange text.

04/15/2019