



04/15/2019





04/15/2019







A photograph of a stone wall, likely made of limestone or a similar light-colored stone. The wall is constructed in a regular pattern of rectangular blocks. A concrete coping runs along the top edge of the wall. In the background, bare trees and a cloudy sky are visible. A date stamp is located in the lower right corner of the image.

04/15/2019



A photograph of a stone wall, likely made of concrete or stone blocks, showing a pattern of rectangular stones. The wall is viewed from a low angle, looking up towards the top right corner. A date stamp '04/15/2019' is visible in the bottom right corner of the image. The sky is visible in the upper right corner.

04/15/2019






04/15/2019



A photograph of a concrete wall. On the left side, there is a vertical column of four large, rectangular concrete blocks. A dark, vertical crack runs down the right side of this column, starting from the top and extending nearly to the bottom. The rest of the wall is made of smaller, irregular concrete blocks. At the bottom left, there is some dark soil and some dry, yellowish-brown grass or weeds. In the bottom right corner, there is a date stamp in orange text.

04/15/2019





04/15/2019









04/15/2019









04/15/2019









04/15/2019





04/15/2019









04/15/2019





04/15/2019