


A close-up photograph of a metal surface, likely a pipe or structural component, showing severe corrosion. The surface is covered in a thick, dark, and flaking layer of rust. Several bright orange-red streaks, possibly from a cleaning agent or paint, run diagonally across the frame. A white arrow points to a small, dark, circular hole in the metal. The word "HOLES" is written vertically in white capital letters next to the arrow.

HOLES