













A close-up photograph of a metal surface, likely a ship's hull, showing a series of vertical ridges. A horizontal line of bolts runs across the middle of the image. The metal surface is heavily corroded, with a reddish-brown rust visible along the boltline and in the creases between the ridges. The text "BOLTLINE CRACKING" is overlaid in blue capital letters in the center of the image.


BOLTLINE CRACKING















91 NORTH
White River Jct.
RIGHT LANE