



10/28/2020





10/28/2020



10/28/2020





10/28/2020



10/28/2020



10/28/2020



10/28/2020



10/28/2020



10/28/2020

A photograph of a paved road surface. A vertical crack runs down the center of the road. In the foreground, there is a large pile of brown, dried leaves and some green grass. A metal guardrail is visible in the background. The date "10/28/2020" is printed in orange text in the bottom right corner.

10/28/2020



10/28/2020





10/28/2020



10/28/2020



10/28/2020



10/28/2020





10/28/2020

BRIDGE
NO.

TF 7137

1
9
7
4

10/28/2020

A photograph showing a corner or joint of a concrete and metal structure. On the left, there is a concrete wall with horizontal lines and some peeling material at the bottom. To the right is a large, dark, rusted metal panel. The ground in the foreground is covered with dry leaves, twigs, and some green grass. A date stamp is visible in the bottom right corner.

10/28/2020



10/28/2020



10/28/2020







10/28/2020



10/28/2020

A photograph showing a concrete foundation wall. On the left is a dark, textured vertical surface. The concrete wall has a horizontal joint and a small, irregular hole or opening near the bottom. Some dry, thin branches and green grass are growing from the ground in front of the wall. The ground is covered with some dry leaves and debris. A date stamp is visible in the bottom right corner.

10/28/2020



10/28/2020





10/28/2020



10/28/2020



10/28/2020



10/28/2020



10/28/2020







10/28/2020



10/28/2020



10/28/2020





10/28/2020



10/28/2020



10/28/2020