



07/30/2020



07/30/2020



07/30/2020



07/30/2020



07/30/2020



07/30/2020



07/30/2020





07/30/2020





BUILT BY
PALMER STEEL CO.
INC.
SPRINGFIELD, MASS.
1928

07/30/2020



07/30/2020





07/30/2020



07/30/2020











07/30/2020



07/30/2020







07/30/2020





07/30/2020



07/30/2020



07/30/2020

A photograph of a green steel bridge structure, likely a truss bridge, taken from a low angle looking up. The main vertical beam on the left is a solid green I-beam. To its right is a truss section with diagonal cross-bracing, also painted green. Numerous bolts are visible at the joints. The background shows a clear blue sky with some light clouds and a dense line of green trees. A date stamp is located in the lower right area of the image.

07/30/2020

A photograph taken from a bridge, looking down at a dense forest. A teal-colored vertical beam is in the foreground, partially obscuring the view. The forest is lush with green trees and foliage. Two power lines run across the top of the image. The date '07/30/2020' is printed in orange in the bottom right corner.

07/30/2020



07/30/2020







07/30/2020



07/30/2020



07/30/2020









07/30/2020





07/30/2020



















07/30/2020







07/30/2020







07/30/2020



07/30/2020



07/30/2020







07/30/2020



07/30/2020





07/30/2020





07/30/2020



07/30/2020





07/30/2020

A photograph of a concrete wall, possibly a retaining wall or foundation, showing signs of weathering and discoloration. To the left of the wall, there is a dense growth of green vegetation, including tall grasses and leafy plants. The wall itself is made of large concrete panels separated by a horizontal joint. A date stamp '07/30/2020' is visible in the lower right corner of the image. There is a rainbow-like lens flare in the upper right corner.

07/30/2020

A photograph showing a green plant with thin stems and small leaves growing in a corner. To the left is a light-colored concrete wall. To the right is a dark green metal structure with a grid of large, round rivets. The ground is covered in gravel and some dry, brown sticks. A date stamp is visible in the bottom right corner.

07/30/2020

BRIDGE
NO.

TH-2808

1
9
9
1

07/30/2020





07/30/2020

This photograph shows the underside of a bridge structure. A large, irregular hole is visible in a dark, weathered steel beam. To the right, a concrete slab is visible, featuring a smaller, more circular hole. The bridge's structural components, including a blue-painted steel beam with rivets, are visible. The date '07/30/2020' is printed in orange at the bottom center of the image.





07/30/2020





07/30/2020





07/30/2020



07/30/2020



07/30/2020



07/30/2020





07/30/2020



07/30/2020



07/30/2020





























































