



09/21/2020









09/21/2020

















09/21/2020



A photograph of a road surface, likely asphalt, showing a significant longitudinal crack. A double yellow line runs diagonally across the upper portion of the image. A metal guardrail is visible in the upper right background. A small branch with green leaves enters from the right side. A date stamp is located in the bottom right corner.

09/21/2020









09/21/2020





09/21/2020









09/21/2020





09/21/2020





09/21/2020





09/21/2020





09/21/2020









09/21/2020





09/21/2020









09/21/2020





09/21/2020





























09/21/2020





09/21/2020

















09/21/2020





09/21/2020



A photograph of a concrete wall, possibly a retaining wall or foundation, with a rough, weathered texture. To the left of the wall, there is a dense thicket of bare, brown, woody branches and some green leaves. The ground in the foreground is dark and covered with fallen brown leaves and some small green plants. The date "09/21/2020" is printed in orange text in the bottom right corner of the image.

09/21/2020









09/21/2020





09/21/2020





09/21/2020





09/21/2020





09/21/2020





09/21/2020