



09/22/2020

The image shows a close-up view of a road surface with two distinct potholes. The road is paved with dark asphalt and shows signs of wear and cracking. In the foreground, a concrete curb runs along the edge of the road, with some dry leaves and debris scattered along its base. In the background, a metal guardrail is visible, supported by concrete posts, with a dense line of green foliage behind it. The date '09/22/2020' is printed in orange text in the bottom right corner of the image.