



07/15/2020





07/15/2020









07/15/2020





07/15/2020





07/15/2020







A photograph of a road surface showing a significant longitudinal crack. The road is paved with asphalt and has double yellow lines. A concrete curb is visible on the right side. A date stamp is present in the bottom right corner.

07/15/2020





07/15/2020





07/15/2020





07/15/2020



A photograph of a road surface with a prominent vertical crack. A concrete curb and a metal guardrail are visible on the right side. Green vegetation is growing along the curb. The date '07/15/2020' is printed in orange at the bottom center.

07/15/2020





07/15/2020









07/15/2020





07/15/2020





07/15/2020





07/15/2020









07/15/2020









07/15/2020





07/15/2020









07/15/2020













07/15/2020









07/15/2020









07/15/2020





07/15/2020





07/15/2020





07/15/2020





07/15/2020





07/15/2020





07/15/2020









07/15/2020





07/15/2020





07/15/2020













07/15/2020













07/15/2020







